

Nickel Troubleshooting Guide

PLATING PROCESS SYSTEMS

BRIGHT NICKEL

Index Type

Troubleshooting Bright Nickel Solutions with Bright Nickel Make-Up

(Index Type)

Symptom	Usual Causes	Correction
Cloudy deposits (MCD and HCD areas)	<ol style="list-style-type: none">1. Low Brightener2. Low pH3. Organic contamination4. Metallic contamination (e.g., Fe, Si, Al, Cr+3)	<ol style="list-style-type: none">1. Increase concentration of Brightener2. Adjust pH3. Carbon treatment*4. High pH + carbon treatment*
Cloudy deposits (LCD areas)	<ol style="list-style-type: none">1. Low Brightener2. Low pH3. Low Bright Nickel Make-Up	<ol style="list-style-type: none">1. Adjust Brightener concentration2. Adjust pH3. Add Bright Nickel make-Up
Dull deposits (LCD area)	<ol style="list-style-type: none">1. High Brightener2. Metallic contamination (e.g., Cu, Zn, Pb, Cd)3. Low Carrier4. High agitation	<ol style="list-style-type: none">1. "Dummy" solution at 4-5 ASF*2. "Dummy" solution at 4-5 ASF*3. Add Carrier4. Reduce agitation rate
Poor leveling	<ol style="list-style-type: none">1. Low Brightener2. Low Carrier3. Low pH4. Low Bright Nickel Make-Up5. Low agitation	<ol style="list-style-type: none">1. Add Brightener2. Add Carrier3. Adjust pH4. Add Bright Nickel Make-Up5. Increase agitation rate
Poor ductility	<ol style="list-style-type: none">1. High Brightener2. Low Carrier3. High pH 4. Metallic contamination (e.g., Zn, Cd)5. Organic contamination	<ol style="list-style-type: none">1. "Dummy" solution at 4-5 ASF*2. Add Carrier3. Adjust pH 4. "Dummy" solution at 4-5 ASF*5. Carbon treatment*
Burning	<ol style="list-style-type: none">1. Low nickel salts/boric acid2. High CD3. Low temperature	<ol style="list-style-type: none">1. Add nickel salts/boric acid2. Reduce CD3. Adjust temperature

4. Low agitation

5. Chromate contamination

6. Metallic contamination
(e.g., Fe, Al, Si)

4. Increase agitation rate

5. High CD "dummy" + high pH
treatment*

6. High pH + carbon treatment*

Skip plating

1. High Brightener

2. Metallic contamination (e.g., Zn, Cd,
Pb)

3. Chromate contamination

1. "Dummy" solution at 4-5 ASF*

2. "Dummy" solution at 4-5 ASF*

3. High CD "dummy" + high pH
treatment*

Poor chromium acceptance

1. High Brightener

2. Low Carrier

1. "Dummy" solution at 4-5 ASF*

2. Add Carrier

3. Inadequate rinsing between Ni and Cr

4. Cr solution out of balance

3. Improve rinsing

4. Adjust Cr solution

High Consumption Carrier

1. High drag-out

2. Excessive carbon usage

3. Very high nickel concentration

1. Use reclaim tank

2. Reduce amount of carbon used

3. Dilute solution

Brightener

1. High concentration of Brightener

1. Reduce concentration of Brightener

2. Low anode area/polarized anodes

2. Increase anode area and/or increase
nickel chloride and/or reduce pH

Bright Nickel Make-Up

1. High drag-out

1. Use reclaim tank

2. Low anode area/polarized anodes

2. Increase anode area and/or increase
nickel chloride and/or reduce pH

Non-Index Type

Troubleshooting Bright Nickel Solutions Without Bright Nickel Make-Up

(Non-Index Type)

Symptom

Usual Causes

Correction

Cloudy deposits (MCD and HCD areas)

1. Low Brightener

2. Low pH

3. Organic contamination

4. Metallic contamination
(e.g., Fe, Si, Al, Cr+3)

1. Increase Brightener concentration

2. Adjust pH

3. Carbon treatment*

4. High pH + carbon treatment*

Cloudy deposits (LCD areas)

1. Low Brightener
2. Low pH

Dull (dark) deposits (LCD area)

1. High Brightener
2. Metallic contamination (e.g., Cu, Zn, Pb, Cd)
3. Low Carrier
4. High agitation

Poor leveling

1. Low Brightener
2. Low Carrier
3. Low pH
4. Low Leveling Agent
5. Low agitation

Poor ductility

1. High Brightener
2. Low Carrier
3. High pH

4. Metallic contamination (e.g., Zn, Cd)
5. Organic contamination

Burning

1. Low nickel salts/boric acid
2. High CD
3. Low temperature
4. Low agitation

5. Chromate contamination
6. Metallic contamination (e.g., Fe, Al, Si)

Skip plating

1. High Brightener

2. Chromate contamination

3. Metallic contamination (e.g. Fe, Al, Si)

Poor chromium acceptance

1. High Brightener
2. Low Carrier
3. Inadequate rinsing between Ni and Cr solutions
4. Cr solution out of balance

High Consumption Carrier

1. High drag-out
2. Excessive carbon usage
3. Very high nickel concentration

Brightener

1. Adjust Brightener concentration
2. Adjust pH

1. "Dummy" solution at 4-5 ASF*
2. "Dummy" solution at 4-5 ASF*
3. Add Carrier
4. Reduce agitation rate

1. Add Brightener
2. Add Carrier
3. Adjust pH
4. Add Leveler
5. Increase agitation rate

1. "Dummy" solution at 4-5 ASF*
2. Add Carrier
3. Adjust pH

4. "Dummy" solution at 4-5 ASF*
5. Carbon treatment*

1. Add nickel salts/boric acid
2. Reduce CD
3. Adjust temperature
4. Increase agitation rate
5. High CD "dummy" + high pH treatment*
6. High pH + carbon treatment*

1. "Dummy" solution at 4-5 ASF*
2. High CD "dummy" + high pH treatment*

3. High pH + carbon treatment*

1. "Dummy" solution at 4-5 ASF*
2. Add Carrier

3. Improve rinsing
4. Adjust Cr solution

1. Use reclaim tank
2. Reduce carbon used
3. Dilute solution

1. High concentration of Brightener
2. Low anode area/polarized anodes
3. High agitation

1. Reduce concentration of Brightener
2. Increase anode area and/or increase nickel chloride and/or reduce pH
3. Reduce agitation rate.

SEMI-BRIGHT NICKEL

Semi-Bright Nickel Troubleshooting

Troubleshooting Semibright Nickel

Symptom	Usual Cause	Correction
----------------	--------------------	-------------------

Cloudy deposits (MCD and HCD areas)		
--	--	--

1. Low leveler
2. Low pH
3. High Make Up additive
4. High STEP Additive
5. Organic contamination
6. Metallic contamination (e.g., Fe, Si, Al, Cr+3)
7. Low agitation

1. Increase concentration of Leveler
2. Adjust pH
3. Reduce Make Up concentration (carbon filter)
4. Discontinue additions temporarily
5. Carbon treatment
6. High pH + carbon treatment
7. Increase agitation

Cloudy deposits (LCD areas)		
------------------------------------	--	--

1. Low Leveler
2. Low pH

1. Adjust Leveler concentration
2. Adjust pH

Dull deposits (LCD area)		
---------------------------------	--	--

1. Metallic contamination (e.g., Cu, Zn, Pb, Cd)

1. "Dummy" solution at 4-5 ASF*

Too Bright		
-------------------	--	--

1. High leveler
2. Low Make Up

1. Reduce Leveler concentration
2. Add Make Up

Poor leveling		
----------------------	--	--

1. Low Leveler
2. Low Make Up
3. Low pH
4. High STEP Additive
5. Low agitation

1. Add Leveler
2. Add Make Up
3. Adjust pH
4. Discontinue additions temporarily
5. Adjust agitation

Poor ductility		
-----------------------	--	--

1. High Leveler
2. Low Make Up
3. High pH
4. Metallic contamination (e.g., Zn, Pb, Cd)
5. Organic contamination

1. Reduce Leveler concentration
2. Add Make Up
3. Adjust pH
4. "Dummy" solution at 4-5 ASF
5. Carbon treatment

Burning		
----------------	--	--

1. Low nickel salts/boric acid

1. Add nickel salts/boric acid

2. High current density (CD)
3. Low temperature
4. Low agitation
5. Chromate contamination

2. Reduce current density
3. Adjust temperature
4. Increase agitation
5. High CD "dummy" + high pH treatment*

Skip plating

1. High Leveler
2. Low Make Up
3. Metallic contamination (e.g., Pb, Zn, Cd, Cr+6)

1. "Dummy" solution at 4-5 ASF
2. Add Make Up
3. "Dummy" solution at 4-5 ASF

High Consumption of: Make Up

1. High drag-out
2. Excessive carbon usage on filter

1. Use reclaim tank
2. Reduce amount of carbon used

Leveler

1. High concentration of Leveler
2. Low anode area (polarized anodes)
3. Organic contamination

1. Reduce concentration of Leveler
2. Increase anode area
3. Carbon treatment (may help)

DUPLEX NICKEL

Duplex Nickel Troubleshooting Troubleshooting Duplex Nickel

Symptom	Usual Cause	Correction
---------	-------------	------------

Poor STEP results

1. Low STEP Additive in semibright nickel
2. Poor Bright Nickel deposit
3. Contamination of semibright nickel solution with sulfur containing material

1. Add STEP Additive to semibright nickel
2. Carbon treatment (may help)
3. Adjust brightener in Bright Nickel solution

Poor corrosion performance

1. See **Poor STEP** results above.
2. Pits present in either Semibright Nickel or Bright Nickel solutions.
3. Particulate matter present (indicated by rough deposits) in either Semibright or Bright nickel solutions.
4. Microporous porous chromium layer not functioning (if used)

2. Correct pitting problem (add anti-pitter and/or carbon treat solution)
3. Filter solutions.
4. Inspect microporous Nickel and/or chromium and correct.

Peeling of Bright Nickel layer from Semibright Nickel layer Overall

1. Drying of Semibright Nickel solution during part transfer.

1. If consistent, insert rinse operation between Semibright and Bright Nickel solutions.

2. Pickup of films during exit from Semibright Nickel or entrance to Bright Nickel solutions.

2. See above and/or carbon treat each solution.

Trailing edges only

Parts are bipolar exiting from Bright Nickel solution

Install live current exit from Bright Nickel (Use approx. 10% of normal rack current)

Leading edges only

Parts are bipolar entering Semibright Nickel solution.

Install live current entrance to Semibright Nickel (Use approx. 10% of normal rack current)

Bottom of part/rack only

Too much current during exit from Semibright Nickel and/or entry to Bright Nickel solutions.

Reduce current density at these points (consider removal of some anode material at these points)

Pattern after Bright Nickel

1. Drying of Semibright Nickel solution during part transfer.

1. If consistent, insert rinse operation between Semibright and Bright Nickel solutions.

2. Drying of foam from Semibright Nickel solution

2. Carbon treat solution to reduce foaming or reduce air agitation to minimize foam.

