

## Special Attention

1. Remove the wooden crate. And check whether the standard or special accessories accord with the packing list or not. Please contact the seller for unconformity.
2. Never attempt to use, operate or adjust the lathe before reading the operation manual and understanding the installation procedure.
3. Wear gaberdine, approved safety goggles and face shield while using the machine.
4. Forbidden to wear gloves, high-heel shoes and skirts.
5. Be subject to alteration without notice during the production procedure.
6. Under the condition of normal use and maintenance, if the operation is not satisfied, please contact the seller.

# CONTENTS

1、 Application .....	1
2、 Main technical specifications .....	2
3、 Transmission system .....	3
4、 Bed assembly .....	10
5、 Head stock .....	16
6、 Tail stock .....	22
7、 Tool post & saddle .....	26
8、 Apron .....	35
9、 Change gear base .....	42
10、 Steady rest & follow rest .....	48
11、 Lathe protection .....	50
12、 Special accessories .....	56
13、 Test run, operation & maintenance .....	58
14、 Lubrication system .....	60
15、 The procedure of processing the common parts ...	62
16、 Transportation & installation .....	65
17、 Electrical part .....	66
18、 Appendix .....	68

# 1. APPLICATION

This machine is suitable for processing cast iron pieces, steel pieces, non-ferrous metal and non-metal pieces up to 250mm(HD210 for 210mm). The size of the spindle bore allows 20mm bar-shaped materials to go or through it. It can work out, cone, step, end surface, grooves, holes (drilling and boring), threads (Metric and Imperial).

With the advantage of high accuracy, rational structure, easy operation & reliable quality, the bench lathe can be fixed on the iron or wooden worktable (the iron work table can be ordered from factory) without the concrete base. We use the cold-reduced trapezoidal steel lead screw to improve the hardness, abrasion resistance and durability of the threads surface, and also to prolong its work life. It's the ideal machine for family maintenance, metals, light machinery, school training, and car repairing, etc. It's proper both for the one to process the piece production and for the factories to produce in batches.

## 2、 MAIN TECHNICAL SPECIFICATION.

	HD210	HD250	CQ6125
Max.swing over bed	210mm	250mm	250mm
Max.swing over gap	320mm	400、550、750mm	400、550、750mm
Metric thread	0.4~3mm	0.4~3mm	0.3-2.5mm
Steps	12 steps		
Spindle bore	20mm		
Tape lf spindle bore	M.T.NO.3		
Range of spindle speeds	125-2000r.p.m		
Steps	6 steps		
Longitudinal feed per spindle revoution	0.1~0.2mm		
Tool post cutting area	14×14mm		
Inch threads	10~44/25.4mm		
Steps	8 steps		
Taper of tail stock pull	M.T.NO.2		
Motor frequency(50、60HZ)	550w/220v-380v		

### Form 1 Form to distinguish the different lathe models

Name \ Model	HD210	HD250	CQ6125
Head stock	See Fif5-2(with oblique head stock)	See Fif5-1(with oblique head stock)	See Fif5-3
Feed box	No	No	See Fig10
Bed assembly	See Fig4-1	See Fig4-1、4-4	See Fig4-2、4-3
Tal stock	See Fig6-2	See Fig6-1	See Fig6-1
Tool post	See Fig7-3	See Fig7-1、7-2	See Fig7-1、7-2
Saddle	See Fig 8-2	See Fig 8-1、8-3	See Fig 8-1、8-3
Apron	See Fig9-1、9-2	See Fig9-1、9-2	See Fig9-1、9-2
Change gear	See Fig11-1	See Fig11-1	See Fig11-2
Base for 3-jaw chuck	No	See Fif5-4	See Fif5-4

### 3、 TRANSMISSION SYSTEM

#### 3.1 See Fig1 Form 2, Fig 3

All the moving force of the spindle in head stock and feed system comes from electric motor. When you open the safety cover, you'll see the transmission structure. The triangle pulley on the motor will drive the spindle directly to reach the high speed at 620, 1000, 2000 r.p.m. If you want to moderate by using the synchromesh pulley which is concatenated on the motor pulley, you can reach the low speed at 125, 210, 420 r.p.m., that is six different speeds from the spindle.

#### 3.2 Feed system

The tool post feed is that the main shaft gear behind the main spindle through the different speed ratio of the change gears, makes 114 lead screw turning. If you operate 608 handle on the apron to shut the half nut, you can get different feed speeds, you can also get different cutting thread pitches.

During the course of the head stock spindle rotation from clockwise cutting direction to reversion, generally the clockwise feed is for right threads cutting. If you want the counter-clockwise rotation to get the left threads, you can take out another set of fixed shaft bolts with 40 teeth from the

standard accessories, and fixed below the spindle to get the relative mesh together with the original fixed 40 teeth shaft bolt. Only in this way can you get the 114 lead screw reverse to realize counter-clockwise feed and left threads cutting.

3.3 Fig 2 is the transmission system for CQ6125 with feed box. CQ6125 is same as HD250 except for the feed box. The parts in the feed box are shown in Fig.10.




Fig.1 Transmission System And Bearing Distribution (HD250, HD210)




Fig.2 Transmission System And Bearing Distribution (Cq6125)




## Form2 Transmission Parts

NO	Name	No. of teeth threads	Module pitch	Serrated form angle	Spiral direction	Related part	Nos in Fig	Notes
1	Belt	19	1.5	20°		15	15024	
2	Change gear	25	1	20°		08	08017	
3	Spindle belt					02	02020	
4	Spindle gear	40	1	20°	right	02	02021	
6	Lead screw		T20×2		left	01	01005	
8	Jam Nut		M14		left	05	05014	
9	Screw Post		M14		right	05	05013	
10	Screw Post		M8×1		left	04	04018	
11	Arbor Plate		M8×1			04	04011	
12	Gear	57	1	20°		06	06016	
13	Gear rack		1.25	20°		01	01009	
14	Gear shaft	17	1.25	20°		06	06014	
15	Nut		T20×2		Right	06	06017	
16	Eccentric					06	06020	
17	Pin					06		GB119-76/5×12
18	Screw Post		M14		left	03	03016	
19	Tailstock sleeve		M14		left	03	03015	
21	Synchromesh mid belt	90	1.5	20°		15	15023	
22	Jam wheel					15	15012	
24	Transition gear	40	1	20°		08	08013	
26	Change gear	80	1	20°		08	08019	
27	Change gear	33	1	20°		08	08025	
28	Change gear	90	1	20°		08	08032	
29	Change gear	90	1	20°		08		B=18
30	Synchromesh serrated belt	124	1.5	20°		15		O type 762
31	Triangle tape					15		
32	Motor wheel					15	15018	JZ7134/550W
33	Motor					15		
34	Gear shaft	17	1			06	06013	

# Form 3 Bearings

No	Name	Type	Specification	Qty	Position
5	Single row taper bearing	2007107	35×62×17	2	Head stock
7	Single row thrust bearing	8101	12×26×9	1	Saddle
20	Single row thrust bearing	8101	12×26×9	1	Tail stock
23	Single row centripetal force bearing	101	12×28×8	2	Jam wheel
25	Single row centripetal force bearing	101	12×28×8	1	Change gear

Fig.3 Motor And Belt Wheels



## Form4 Motor & pulley transmission

No.	Excused standard no.	Name	Qty r	Notes
1501	GB96-52-67	Nut	3	M5
1502	15023	Synchromesh mid pulley	1	
1503	15021	Bearing	1	
1504	15020	Shaft	1	
1505	15022	Cover	1	
1506	GB96-76	Washer	1	12
1507	GB97-76	Washer	1	10
1508	GB52-76	Nut	1	M12
1509	GB52-76	Nut	1	M10
1510	GB54-76	Nut	1	M12
1511	GB818-76	Screw	4	M5×8
1512	15027	Cover	1	
1513	GB30-76	Threaded bolt	3	M10×20
1514	15025	Washer	1	
1515	15016	Washer	1	
1516	15026	Fan shaped support	1	
1517	15030	Support	1	
1518	GB97-76	Washer	1	8
1519	GB818-76	Screw	2	M5×12
1520		Serrated belt	1	M1.5×Z124
1521		Triangle belt	1	Otype762
1522	15015	Shaft	1	
1523	GB30-76	Bolt	1	M8×25
1524	15014	Shaft	1	
1525	15012	Jam wheel	1	
1526	101	Single row centripetal force bearing	2	12×28×8
1527	GB894-76	Spaver	1	12
1528	15013	Quill	1	
1529	R71-1	Oil seal	1	6
1530	GB894-76	Spacer	1	12
1531	15031	Washer	1	
1532	GB894-76	Spacer	1	12
1533	GB893-76	Spacer	1	28
1534	15029	Plate	1	
1535	15028	Cover	1	
1536	GB70-76	Screw	1	
1537	15017	Spacer	1	
1538	15018	Pulley	1	
1539	GB818-76	Svrew	5	M5×8
1540	15024-1	Spacer	1	
1541	15024	Pulley	1	
1542		Hinge	1	75
1543	15024-2	Spacer	1	
1544	JZ7134	Motor	1	400/370W 500/550W
1545	GB97-76	Washer	4	8
1546	GB30-76	Bolt	4	M8×25

#### 4.BED ASSEMBLY

See Fig 4-1,4-2,4-3,Form5.

All the components will be assembled on the bed which is made of HT200 cast iron as the lathe body material after eliminating its internal stress, and it can be used for a long time without deformation, with adequate hardness to bear the cutting load, the fine processed two lozenge tracks can supply easy linear sliding for saddle, tail stock when processing parts.

Before delivery of the lathe, the moving precision of the lead screw & gear rack on bed body has been calibrated, customers do not have to adjust it.



Fig.4-1 Bed Assembly(HD250、HD210)




Fig.4-2 Bed Assembly(CQ6125 With switch lever)




Fig.4-3 Bed Assembly(CQ6125)





Fig.4-4 Bed Assembly(CQ250 With switch lever)





## Form5 Bed Assembly(Fig4-1, Fig4-2, Fig4-3, fig4-4)

No.	Excused standard no.	Name	Qty	Notes
101	01001	Lathe Body	1	400、500、750
102	GB70-85	Screw	1	M8×16
103	01019B/1	Long Gera rack	1	
104	01019/B/2	Short gear rack	1	
105	GB819-85	Screw	6	M5×16
106	GB879-86	Elastic bin	1	4×12
107	01015	Screw post	1	
108	GB115-89	Oil seal	2	Φ6
109	GB70-85	Screw	4	6×16
109A	GB70-85	Screw		6×45
110	GB118-86	Taper pin	2	6×22
110A	GB118-86	Taper pin	4	6×30
111	01018	Right back up	2	
111A	01029	Post support	1	
112	01012	Commection puili	1	
113	GB117-86	Taper pin	1	4×20
114	GB1096-79	Key	2	4×16
115	GB70-85	Screw	1	M4×6
116	01014	Adjusting gland	3	
117	01012	Left back up	1	
118	01028	Positioning loop	1	
119	GB829-86	Elastic bin	1	4×26
120	01022	Swith lever	1	
121	01030	Switch shaft	1	
122	GB70-85	Screw	1	M6×20
123	01033	Switch block	2	
124	GB70-85	Screw	1	M6×20
125	HZ-B/10A	Combination switch	2	
126	J31-3A	Key	1	5×5×24
127	GB879-86	Elastic bin	1	4×20
128	01024	Hand wheel base	1	
129	01025	Hand wheel post	1	
130	GB4141.14-84	Plastic sleeve	2	8×40
131	GB2089-50	Spring	1	Y11.2×6×16
132	GB70-85	Screw	1	M5×10
133	01023	Support		
134	GB894.1-86	Retaining ring		25

## 5、 HEAD STOCK

See Fig 5-1, Fig5-2, Fig5-3, Fig5-4.

Due to the adoption of cone pulley belt to transmit, the structure of the head stock does not become complicated, it is mainly composed of head stock base, shaft, bearings, retaining rings, pulley, nut, etc.

Head stock is important part of the lathe, it will deal with the precision or roughness of the work parts, and it's made with high precision. So the high precision 2007107D grade of single row taper bearings are used for the supports of the main shaft, it can bear the load coming from the radial and axial direction, ensure the main shaft to remain the good precision of rigidity and revolution. The clearance of the bearings for the spindle has been well adjusted before delivery, customers don't have to adjust again. When the lathe is used long and the precision becomes low, also cutting with vibration, then it needs adjusting.

Fig.5-1 Head Stock(HD250)




Fig.5-2 Head Stock(HD210)





Fig6 Head stock (Fig5-1, Fig5-2)

No.	Excused standard no.	Name	Qty	Notes
201	02014	Oil seal	1	
202	2007107	Gearing	2	35×62×17
203	02013	Oil seal	1	
204	GB818-76	Screw	4	M3×8
205	02016	Face cover	1	
206	02014A	Oil seal	1	
207	02015	Loop	1	
208	02020	Pulley	1	
209	GB812-76	Nut	2	
210	02021	Spindle gear	1	
211	GB818-76	Nut	3	M5×10
212		Switch	1	
213	02011	Head stock	1	
214	GB1096-79	Key	1	4×40
215	GB70-76	Screw	3	M6×16
216	02012	Spindle	1	
217	02018	Positioning loop	3	


Fig.5-3 Head Stock(CQ6125)



## Form7 Head stock (Fig5-3)

No.	Excused standard no.	Name	Qty	Notes
201	15032	Electric box	1	
202	02011	Head stock body	1	
203	02016	Face cover	1	
204	GB818-86	Screw	4	M3×6
205	GB70-85	Threaded bolt	1	M6×12
206	GB96-85	Washer	2	6
207	02027	Shaft	1	
208	GB1096-86	Key	1	4×20
209	02028	Quill	1	
210	08019	Loop	1	
211	08018A	Gear	1	Z60
212	08016	Gear	1	Z50
213	GB5783-86	Bolt	1	M6×16
214	GB812-88	Nut	1	M27×1.5
215	02020	Pulley	2	
216	02021	Gear	1	Z45
217	02025	Loop	1	
218	GB297-64	Bearing	1	2007107
219	02013	Oil seal	1	
220	02013	Oil seal	1	
221	GB297-64	Bearing	1	2007107
222	02013	Oil seal	1	
223	02012	Spindle	1	
224	GB1096-86	Key	1	4×50

Fig.5-4 3-jaw Chuck Base(HD250、CQ6125)



Form8 3-jaw chuck base(Fig5-4)

No.	Excused standard no.	Name	Qty	Notes
901	GB55-76	Nut	3	M10
902	09012	Bolt	3	
903	GB21-76	Bolt	3	M8×25
904	09011	3-jaw chuck base	1	

## 6、 TAIL STOCK

See Fig 6-1,6-2

Tail stock is consisted of its base,sleeve,screw post,etc.It can be moved along the guiding rails, you can screw 304 Nut to fasten it at any position on the guiding rails. Then turn 320 Hand wheel to get the tail stock sleeve moving forward and backward to finish boring, tapping, reaming, cutting, etc. The manufacturing accuracy of the tail stock has reached the allowable error range. The zero central position line is carved in front of the 305 tail stock body and 326 tail stock base.If you need moving the tail stock axis to left and right side when cutting, adopt the following measures.

6.1 Loosen 304 Nut,you can move the tail stock.

6.2 Loosen 315 Nut

6.3 Adjust 301 screw slightly to move tail stock for the right process requirement.

6.4 Fasten 315 screw and 304 Nut to start operation.



Fig.6-1 Tail Stock(HD250、CQ6125)





Fig.6-2 Tail Stock(HD210)



Form 9 Tail stock prats(Fig6-1, Fig6-2)

No.	Excused standard no.	Name	Qty	Notes
301	GB70-76	Screw	2	M8×30
302	03013	Nut	1	
303	GB97-76	Washer	1	B12
304	GB55-76	Nut	1	M12
305	03011	Tail stock base	1	
306	8101	Single row thrust bearing	1	12×26×9
307	03016	Screw post	1	
308	03015	Sleeve	1	
309	03020	Jam Quill	1pair	
310	GB97-76	Washer	1	B8
311	03021	Screw Post	1	
312	03022	Handle	1	6
313	R71-1	Oil cup	2	
314	03019	T-shqped key	1	M6×16
315	GB75-76	Screw	1	M5×16
316	GB70-76	Screw	4	
317	03017	End cover	1	4×30
318	GB879-76	Nut	1	
319	04022	Pinch cock	1	
320	03018	Hand wheel	1	
321	06027A	T hreded bolt	1	
322	06027	Quill	1	
323	04021	Ring	1	
324	GB30-76	Threaded bolt	1	M12×100
325	03014	Gland	1	
326	03012	Gase	1	
326A	HD210-03012	Base	1	
327	GB1079-86	Key	1	4×12

## 7、 TOOL POST & SADDLE

See Fig 7-1,7-2,7-38-1,8-3.

Tool Post is connected with saddle, it' s mainly consisted of slide, screw post, adjustable iron, tool post, turn plate base, etc. It can be moved longitudinally & transversely through locomotive and manual operation. The turn plate of the tool post can have 60° revolution from left to right when needed, the dividing disk is fixed on the handle, using the mark can help process accurate circular column, taper and plane , etc. During the long time use of the lathe, the dovetail guide of the saddle, tool post slide, saddle clip, they' ll abrade the guiding rails, the saddle bolts will also abrade the nuts and cause the bigger clearance ,low precision . Adopt the following measures to adjust the clearance.

- 1、 To adjust the clearance of the saddle slide dovetail, tool post slide dovetail and saddle clip is to loose 513Nut, adjust 514 nut till to eliminate the clearance, then screw up 513 nut. Using the same way to adjust the clearance of the tool post slide and the clearance of 518 saddle to get the stable slide without looseness.
- 2、 To adjust the clearance between the saddle bolts and nuts is to dismount 539 support and 501 nuts , properly screw up the two 541 screws, you' ll see the clearance obviously

becomes small. After installing again , turn 533 hand wheel in clockwise & counter clockwise direction. With the idle running amount decreased,the process precision is improved.

Fig.7-1 Tool Post(HD250、CQ6125)




Fig.7-2 Tool Post(HD250A、CQ6125A)





Fig.7-3 Tool Post(HD210)



From 10 Tool rest(Fig7-1,7-2,7-3)

No.	Excused standard no.	Name	Qty	Notes
401	04025	Turn plate base	1	
402	04024	Gland	1	
402A	04024A	Gland	1	
403	GB30-76	Threaded bolt	2	M8×20
403A	GB41-85	Nut	2	M6
404	04011	Turn plate	1	
404A	HD210-04011	Turn plate	1	
405	04015	Threaded bolt	1	
405A	HD210-04015	Threaded bolt	1	
406	GB54-76	Nut	3	M4
407	GB75-76	Screw	3	M4×20
408	GB75-76	Screw	1	M4×12
409	GB54-76	Nut	1	M4
410	04014	Locating pin	1	
411	04013	Follow rest	1	
411A	H0D210-04013	Follow rest	1	
412	GB85-76	Screw	8	
413	03022	Handle	1	
414	04017	Handle base	1	
415	04016	Washer	1	
416	Q81-1	Spring	1	
417	04012	Slide	1	
418	04026	Filling iron	1	
419	GB879-76	Cylinder pin	1	
420	04018	Screw post	1	3×10
421	GB879-76	Key	1	
422	R71-1	Oil cup	2	3×10
423	04020	Srpport	1	
424	GB70-76	Screw	2	
425	04022	Spring slice	1	
426	04023B	Handle	2	
427	GB5781-76	Nut	2	M8
428	GB97-76	Washer	1	
429	04023	Hand wheel	1	
430	04021	Calibration ring	1	
431	GB65-76	Screw	4	M6×16
432	GB897-76	Cylinder pin	2	4×16
433	04024	Position bolt	1	
434	GB37	T-shaped bolt	2	M6×22
435	GB41-85	Nut	2	M6
436	04025	Shaft	1	
437	GB876-84	Rivet	2	2×4
438	GB37	T-shaped bolt	2	M6×22



Fig.8-1 Saddle(HD250、CQ6125)




Fig.8-2 Saddle(HD210)





Fig.8-3 Saddle(HD250A、CQ6125A)



From 11 Saddle(Fig8-1, Fig8-2, Fig8-3)

No.	Excused standard no.	Name	Qty	Notes
501	GB70-85	Svrew	1	M5×10
502	05015	Washer	1	
503	R71-1	Oil vup	9	
505	05012	Slide	1	
501A	HG210-05012	Slide	1	
505B	05012A	Slide	1	
506	05011	Saddle	1	
507	GB70-85	Screw	4	M5×20
508	GB70-85	Screw	1	M8×20
509	GB70-85	Screw	4	M6×35
510	05027	Protection board	2	
511	GB70-86	Screw	2	M8×30
512	05030	Oil scraper felt	2	
513	GB75-76	Screw	4	M5×25
514	GB52-76	Nut	4	M5
515	05026	Brake iron	1	
516	05027	Oil scraper felt	1	
517	GB67-76	Screw	8	M3×12
518	05021	Brake clip	1	
519	05022	Brake iron	1	
520	GB70-85	Screw	4	M5×16
521	GB70-76	Nut	5	M4
522	GB54-76	Screw	5	M4×16
523	05029	Protection board	2	
524	GB1079-86	Key	1	4×8
525	GB70-85	Screw	3	M5×22
526	GB1096-79	Spring slice	1	
527	05032A	Washer	1	
528	GB70-85	Screw	1	M6×10
529	05024	Brake clip	1	
530	05023	Brake clip	1	
531	06027A	Handle bolt	1	
532	06027	Handle casing	1	
533	05018	Hand wheel	1	
534	GB301-84	Hearing8101	1	12×26×9
535	05019	Calibration ring	1	100 格
536	05031	Bearing base	1	0.02mm
537	GB301-84	Beaoring 8101	1	12×26×9
538	05013	Lead screw	1	
539	05017	Screw base	1	
540	05014	Nut	1	Metric2mm
541	gb75-76	Screw	2	M4×12
542	gb70-85	Screw	2	M8×20

## 8、 APRON

See Fig9-1,9-2.

Apron is the longitudinal transmission part on tool post . It can realize locomotive and manual operation measures during cutting .Apron is mainly consisted of its base,gears, shafts, half-nuts, operation handle, etc.


During the running of the lathe, push 608 handle down about  $45^{\circ}$ , the half nut with the revolution function of the 601 trough plate will get the mesh on the lead screw. Meanwhile the tool post may move forward and the slow or fast longitudinal preselected feed amount is based on the table on the change gear. During the completion of the process, move the handle of the half nut up, push in 619 hand wheel, you can withdraw the tool post to the original position. During the locomotive feed period, you'd better pull out the hand wheel to keep the hand wheel in still state for safe operation.

In order that the threads cutting and feed amount accord with the process precision, to shut or open 630 half nut is ensured by the stable slide of the dovetail guide without looseness.

During long time use of the lathe, the guide is hard to avoid from abrading .To adjust the clearance between the dovetail

guide and half nut is a must .The method is to loosen 606 nut, adjust 605 nut to proper position, that is, not too loose and not too tight without getting stuck, then tighten the nut.


Fig.9-1 Apron



Form 12 Apron(Fig9-1)

No.	Excused standard no.	Name	Qty	Notes
601	06020	Notched joint	1	
602	GB117-76	Circular cone pin	1	
603	06012	Shaft puill	1	
604	06011	Apron base	1	
605	GB75-76	Screw	3	
606	GB54-76	Nut	3	
607	06021	Rotation shaft	1	
608	03022	Handle	1	
609	GB308-77	Steel ball	1	
610	Q81-76	Spring	1	
611	06026	Fixed handle	1	
612	GB73-76	Screw	1	
613	GB73-76	Screw	1	
614	GB70-76	Screw	3	
615	06024	Quill	1	
616	GB117-76	Circular cone pin	1	
617	06027A	Bolt	1	
618	06027	Handle casing	1	
619	03018	Hand wheel	1	
620	GB70-76	Screw	3	
621	06025	Quill	1	
622	06013	Gear shaft	1	
623	06012	Quill	1	
624	06016	Gear	1	
625	06015	Quill	1	
626	GB1096-79	Key	1	
627	06014	Gear shaft	1	
628	GB71-76	Screw	2	
629	GB54-76	Nut	1	
630	GB73-76	Svrew	1	
631	06017	Half nut	1 组	
632	06019	Adjustable	1	
633	GB119-76	Cylinder pin	2	

Fig.9-2 New model of Apron






Form 13 New model of apron(Fig9-2)

No.	Excused standard no.	Name	Qty	Notes
601	06011B-1	Apronbase	1	
602	GB1069-79	Key	1	C5×8
603	06014A	Gear shaft	1	
604	06017A	Half nut	1	
605		Shaft quill	2	B2015
606	06013B	Gear shaft	1	
607	GB1096-79	Key	1	4×14
608	06016A	Gear	1	
609	06038	Eccentric wheel	1	
610	GB119-86	Cylinder pin	1	10×45
611	06037	Stir arm	1	
612	GB879-86	Elastic pin	2	4×16
613	06011B-2	Apron cover	1	
614	GB118--86	Taper pin	2	6×22
615	GB70-85	Screw	2	M8×12
616	06025A	Quill	1	
617	GB70-85	Screw	3	M4×10
618	06024	Quill	1	
619	GB70-85	Screw	3	M4×10
620	06036	Calibration ring	1	
621	04022	Spring slice	1	
622	06039	Shaft	1	
623	06023	Handle end	1	
624	GB78-85	Screw	2	
625	03022	Handle	1	M6×20
626	GB308-77	Steel ball	1	φ5
627	Q81-1	Spring	1	0.7×5×25
628	GB73-85	Screw	2	M6×10
629	03018A	Hand wheel	1	
630	06027	Quill	1	
631	06027A	Threaded bolt	1	
632		Quill	1	B1208

Fig.10 Feed Box(CQ6125)



Form 14 Feed box(Fig10)

No.	Excused standard no.	Name	Qty	Specification
701	07023	cover	1	
702	GB276-86	Bearing	1	1000802
703	07026	Gear	1	
704	GB1096-86	Key	1	4×55
705	07024	Shaft	1	
706	GB1096-86	Key	1	4×55
707	07025	Gear	1	
708	GB276-86	Bearing	1	1000802

709	07023	Cover	1	
710	GB68-86	Screw	4	M5×8
711	07011	Feed box	1	
712	07027	Back cover	1	
713	07012	Face plate	1	
714	GB818-88	Screw	4	M3×6
715	GB70-85	Screw	4	M5×18
716	07029	Plate	1	
717	JB1000	Oil plug	1	M10×1
718	07018	Shift fork	2	
719	GB818-88	Screw	2	M3×6
720	07030	Plate	2	
721	GB73-85	Spring	4	M6×8
722	GB2089	Steel ball	4	0.7×5×19
723	GB308-85	Steel ball	4	
724	07017	Handle	2	
725	02016	Con nection block	2	
726	GB894.2-86	Spacer	2	
727	GB1096-86	Key	3	4×8
728	GB70-85	Threaded bolt	2	M8×90
729	GB118-89	Circular cone pin	2	
730	JB1000	Oil plug	1	M10×1
731	GB70-85	Screw	2	M6×90
732	GB1160.1-79	Oil window	1	
733	GB70-85	Screw	3	M5×20
734	HG4-691	Oil seal	1	15×30×10
735	070156	Cover	1	
736	GB276-89	Bearing	1	202
737	07022	Gear shaft	1	
738	07020	Gear	1	
739	GB276-89	Bearing	1	202
740	GB70-85	Screw	1	M5×25
741	GB1096-86	Key	1	4×8
742	07021	Spacer	1	
743	GB076-89	Bearing	1	202
744	07020	Gear	1	
745	07019	Gear shaft	1	
746	GB276-89	Bearing	1	103
747	07014	Cover	1	
748	HG4-691	Oil seal	1	

## 9、 CHANGE GEAR

9.1 See Fig 11-1(HD210,HD250)

Change gear part is consisted of change gears, bolts, nuts, etc.

The change gear is fixed on the left back up of 101 lead screw, in the light of the table plate of 15029 Chang gear to collocate the cutting threads, the change gears for the speed ratio of feed amount, and swing 833 change gear to ensure around 0.1mm transmission gap between the gears, then fasten 835 screw.

The fixed 825 bolt below the main shaft is used for the right threads cutting and clockwise feed. After another set of fixed bolts erected, we can get the combination transmission, and the lead screw will change from its clockwise direction to reversal, and process the cutting of left threads and the counter clock wise feed.

For the metric & inch threads cutting, refer to the table plate on the change gear to collocate the gears. The measurement of the change gear to collocate the gears. The measurement of the feed amount is based on the work piece, surface inelegance level and process accuracy.

When it's not ideal for the feed of work piece procession, the change gear system can be added through careful calculation in accordance with operator's requirement. The

factory can supply the change gears. If the counted number of teeth can not meet the satisfaction, adopt the similar gear to be instead, during the collocation. The relation between the transmission shaft must satisfy the condition of  $Z_3+Z_4 > Z_2+Z_5+2$ . otherwise, the gear top of  $Z_2$ & $Z_5$  will hit together and lead to fail.

For example: Request feed distance 0.3mm/Spindle round.

Given: Gear on spindle  $Z=40$ .

$$\text{Feed distance} = \frac{Z_1}{Z_2} \times \frac{Z_3}{Z_4} \times \frac{Z_5}{Z_6} \times t$$

Screw distance  $t = 2$

$$\text{Solution} = \frac{0.3}{2} = \frac{10 \times 1.5 \times 2}{20 \times 2 \times 5} \times \frac{40}{80} \times \frac{60}{80} \times \frac{30}{75}$$

$$\text{Feed distance} = \frac{40}{80} \times \frac{60}{80} \times \frac{35}{75} \times 2 = \frac{60}{200} = 0.3(\text{mm})$$





Fig.11-1 Change Gear(HD210,HD250)



# Form 15 CHANGE GEAR(Fig11-1)

No.	Excused standard No.	Name	Qty.	Notes
801	08032	Change gear	2	Z90
802	08019	Change gear	2	Z80
803	08023	Change gear	1	Z70
804	08020	Change gear	1	Z52
805	08027	Change gear	1	Z50
806	08022	Change gear	1	Z42
807	08026	Change gear	1	Z40
808	08025	Change gear	1	Z33
809	08018	Change gear	1	Z60
810	08029	Washer	1	
811	GB891-76	Spacer	1	
812	GB68-76	Screw	1	M5X8
813	08017	Change gear	1	Z25
814	08028	Change gear	1	Z75
815	08016	Bolt	2	
816	GB52-76	Nut	2	M12
817	R71-1	Oil cup	2	
818	08024	Change gear	1	
819	08021	Change gear	1	
820	08037	Open washer	2	
821	101	Rolling bearing	1	12×28×8
822	08013	Transition gear	1	Z40
823	GB894-76	Spacer	1	12
824	08036	Washer	1	
825	08012	Fixed bolt	1	
826	08012B	Washer	1	10
827	GB818-85	Screw	2	M5X8
828	GB97-76	Washer	1	6
829	GB65-76	Screw	1	M6X10
830	08035	Baffle-plate	1	
831	08030	Rolling bearing	2	
832	08038	Washer	3	
833	08033	Change gear	1	
834	08031	Square not	2	
835	GB70-76	Screw	1	M6X35

9.2 See Fig. 11-2(CQ6125)


Change gear section is consisted of change gears, shaft bolt, fixed shaft bolt, square nut etc. Change gear is fixed on the left of feed box. According to the speed ratio on the table plate to configure the cutting threads, feed amount, and change gears, swing the frame, ensure the rotation gap between frame and gears around 0.1mm, then fix the screw.

Form 16 CHANGE GEAR WHEEL BOX (Fig11-2)

No.	Excused standard No.	Name	Qty	Notes
801	R71-1	oil cup	2	6
802	GB6172-86	thin nut	4	M10
803	GB97.1-86	washer	2	10
804	08018A	change gear	1	Z60
805	GB1096-86	key	2	4X12
806	08013	sliding bearing	2	
807	08012	bolt	2	
808	08019A	change gear	1	Z80
809	08038A	spare	2	
810	08017	change gear	2	Z40
811	GB70-85	bolt	1	M5X16
812	01020	washer	1	
813	08014	change gear	1	Z100
814	08019	quill	1	
815	GB5781-86	threaded bolt	1	M8X25
816	08011	change gear	1	
817	08035	baffle-plate	1	
818	GB52-76	nut	2	M8



Fig.11-2 Change Gear(CQ6125)



## 10、 FOLLOW REST & STEADY REST

See Fig 12, Fig 13.

The follow rest is used to process slender shafts, use 10-27 screw to fix is on the saddle when operating, turn 10-02 adjustable bolt to make 10-03 supports touch the work piece with proper gyration and move with the cutter. It can ensure the workpiece. Procession to bear the cutting force without bending and deformation. It can abate vibration and ameliorate the surface of the work piece inelegance level.

The steady rest is basically same as the follow rest in use and function principle. The difference is that it's fixed on the lead screw and can't move with cutter. It has three support feet, just like one more pivot for the work piece, so it's used more frequently than follow rest. Such as when processing the medium length shafts it can be used as the positioning support.

Fig.12 Follow Rest





Fig.13 Steady Rest



## Form 17 FOLLOW REST (Fig. 12)

No.	Excused standard No.	Name	Qty	Notes
1001	11014	screw	2	take to use
1002	11012	adjustable threaded bolt	2	take to use
1003	12012	support	2	
1004	GB97-76	washer	2	10
1005	12011	follow rest base	1	
1006	GB52-76	nut	2	M10
1007	GB30-76	threaded bolt	2	M8X30
1008	GB97-76	washer	2	8

## Form 18 STEADY REST (Fig. 13)

No.	Excused standard No.	Name	Qty	Notes
1011	11013	support	3	
1012	11011	steady rest base	1	
1013	11014	screw	3	
1014	11012	adjustable	3	
1015	GB97-76	washer	3	10
1016	GB6170-86	nut	3	M10
1017	GB41-86	nut	1	M12
1018	GB97-76	washer	1	12
1019	03014	clip	1	
1020	GB8-76	threaded bolt	1	M12×70

## 11. PROTECTION OF THE LATHE


In order to ensure the security, and avoid unexpected hurt, we supply many kinds of safety devices for customers to order properly.

### 11.1 Chuck protection

There are two kinds of chuck protection devices. See Fig

14-1 The glass protection cover, which is fine & pretty, can prevent from being hurt by the chuck rotation. see Fig. 14-2 the chuck cover with cutting power device, when it's lifted, the power is cut off to ensure security.


Fig. 14-1 Organic Glass Chuck Cover



Form 19 Organic glass chuck cover ( Fig. 14-1)

No.	Excused standard No.	Name	Qty	Notes
1	GB6170-86	nut	1	M8
2	02024	bearing post	1	
3	GB6170-86	nut	1	M3
4	GB818-86	screw	1	M3×30
5	02025	chuck cover	1	
6	GB6170-86	nut	2	M5
7	02023	support	1	

Fig.14-2 Chuck Cover(With cutting power device)



Form 20 Chuck cover ( With cutting power device) ( Fig. 14-2)

No.	Excused standard No.	Name	Qty	Notes
1	GB79-86	Elastic pin	2	4x20
2	02029	Switch block	1	
3	GB79-86	Elastic pin	1	4x10
4	02031A/2	Shaft	1	
5	02031A	Chuck cover	1	
6	02031A/3	Glass	1	
7	GB818-86	Screw	4	M3X6
8	GB6170-86	Nut	4	M3

## 11.2 The safety proof of leadscrew

Lead screw cover can effectively avoid hair, clothing, etc. from catching.

There are two kinds of screw covers. The helical cover is used for both new & old apron, but the bar-type cover is only used for new model of apron.

Fig. 15-1 Helical Safety Cover for lead screw




Fig.15-2 Helical Safety Cover For Lead Screw  
(Used for new model of apron)







Fig.15-3 Bar-Type Safety Cover For Leadscrew  
(Used for new model of apron)



Form 21 SAFETY GUARD FOR LEAD SCREW ( Fig. 15-2,  
15-2, 15-3)


No.	Excused standard No.	Name	Qty	Notes
1	07032	Left backup quill	1	for CQ6125
2	GB70-85	threaded bolt	6	M4×10
3		helical safety jacket	2	
4	06040	support	2	
5	GB68-85	screw	4	M5×8
6	01014A	adjustable gland	2	
7	06041	joint board	2	For new model of apron
8	GB70-85	thread bolt	4	M4×10
9	01032	safety cover for leadscrew	1	For new model of apron
10	GB818-86	screw	2	M6×8

## 12.SPECIAL ACCESSORIES

In order to be more convenient to use the lathe, we have prepared some special accessories for option, but some extra payment needed.

For the special accessories, see Fig. 16, Form 22

Fig.16 Special Accessories




No.	Excused standard No.	Name	Qty	Notes
1	16015	splash guard	1	
2	16014	oil tray	1	
3	16012	right foot stand	1	
4	16016	front baffle	1	
5	16013	back baffle	1	
6	16011	left foot stand	1	
7		4-jaw chuck base	1set	125mm
8	14011	face plate	1	

## 13、 TEST RUN, OPERATION & MAINTENANCE

Fig. 17, (From 23)

- 13.1 Read the operation manual carefully when operating the lathe at the beginning, try to know the functions of the operating handles.
- 13.2 Before starting, clean the lathe & refer to the lubrication fig. to fill the lubrication oil.
- 13.3 Check whether the transmission belt & the selection of the feed amount is rational or not, whether the gear collocation of the change gear system can meet the requirement or not.
- 13.4 Close the safety cover when the lathe is running, forbid opening the safety cover to use the belt, changing speeds and collocate the change gears.
- 13.5 Starting the motor's push button, pay attention to the above reminding. If you want to make the motor turn clockwise and counterclockwise quickly, pause for at least 3 seconds in order not to damage the electric elements.
- 13.6 Whenever the malfunction happens, stop using it immediately and check it.
- 13.7 Keep the lathe clean, clear away the iron flakes, clean the surfaces of the lead screw and sliding part, and smear oil to prevent from rusting.

Fig.17 Controlling part



## Form 23 Controlling part (Fig 17)

No. sin fig	Name	Uses	Notes
1	Switch	To vary spindle to turn clock wise & counter-clock wise	Head stock
2	Green button	To control the connection and	Head stock
3	Red button	To control the connection of relay	Head stock
4	Main switch	To control connection and disconnection of the lathe	Head stock
5	Handle	To control the saddle to move forward and backward longitudinally	Head stock
6	Handle	To control the apron to move forward and backward longitudinally	Apron
7	Handle	To fix and loosen the tool post	Tool post
8	Handle	To control the slide to move forward & backward	Tool post
9	Handle	To control the half nut to connect & disconnect	Feed box
10	Handle	To lock & loosen the quill	Tail stock
11	Handle	To control the quill to move forward & backward longitudinally	Tail stock
12	Handle	To open and close tool box	Support

## 14. LUBRICATION SYSTEM

See Fig 18 (Form 24)

To keep regular running, the operators are required to use appointed machine oil stipulated in the lubrication fig, fill it periodically to reduce the abrasion, and elongate its working life.




Fig.18 The Distribution Of The Lubrication Position

## Form 24 Lubrication points (Fig 18)

No. sin fig	Name of lubrication position	Name of lubrication part	Period	Type of oil	Injection tool
1	Fixed bolt of transition gear	Oil cup	Once per shift	203 machine oil	Oiler
2	Support	Oil cup	Once per shift	203 machine oil	Oiler
3	Screw post	Oil cup	Once per shift	203 machine oil	Oiler
4	Tool post slide	Oil cup	Once per shift	203 machine oil	Oiler
5	Quill	Oil cup	Once per shift	203 machine oil	Oiler
6	Screw post	Oil cup	Once per shift	203 machine oil	Oiler
7	Support	Oil cup	Once per shift	203 machine oil	Oiler
8	Mid pulley shaft	Oil cup	Once per shift	203 machine oil	Oiler
9	Change gear	Oil cup	Once per shift	203 machine oil	Oiler
10	Change gear bolt	Oil cup	Once per shift	203 machine oil	Oiler
11	Guiding rail	Oil cup	Once per shift	203 machine oil	Oiler
12	Slip board	Oil cup	Once per shift	203 machine oil	Oiler
13	Screw post	Oil cup	Once per shift	203 machine oil	Oiler
14	Sslip board	Oil cup	Once per shift	203 machine oil	Oiler
15	Guiding rail	Oil cup	Once per shift	203 machine oil	Oiler
16	Screw bolt support	Oil cup	Once per shift	203 machine oil	Oiler
17	Feed box	Oil cup	Once per shift	203 machine oil	Oiler
18	Guiding rail	Oil cup	Once per shift	203 machine oil	Oiler
19	Support	Oil cup	Once per shift	203 machine oil	Oiler
20	Feed box	Oil cup	Once per shift	203 machine oil	Oiler
21	Guiding rail	Oil cup	Once per shift	203 machine oil	Oiler
22	Screw post	Direct injection	Once per shift	203 machine oil	Oiler

## 15. THE PROCEDURE OF PROCESSING THE COMMON PARTS

### 15.1. Preparations

15.1.1 Set the work piece on the chuck, check the excircle.

15.1.2 Select and fix the cutter on the tool post.

15.1.3 In the light of the size and material of the work piece to select the running speed and feed amount properly.


15.1.4 Adjust the belt, change gear base to collocate the change gears.

15.1.5 Switch on the starting button to check weather the cutting



end and the feed amount are correct or not.

- 15.2. The procedure to process the circular column parts. Firstly finish the above steps, move the hand wheel of the apron to the right end of the work piece, turn the handle of the saddle to have the cutting end touch the work piece, push the half nut handle to get automatic feed, repeat the cutting and measuring until reaching the right size of the work piece.



- 15.3. The procedure to process the circular cone parts.


The operation is similar as processing the circular column part with the difference of taper, the taper is divided into outer cone and inner cone, there're two ways to process it.

#### 15.3.1 Manual operation

According to the required taper of the work piece, turn the tool post to the right angularity of the work piece and fix it, repeat the cutting to get the needed shape.

#### 15.3.2 Automatic feed.

Processing the taper automatically is to use the characteristic which the tail stock can be moved and adjust the feed. To process the long circular cone part with small angularity, adopt the way of clamping within the two top centers, make the center of the tail stock sleeve offset the main shaft center to keep the same angularity as the work piece, repeat the automatic feed till completion of cutting.



$$S = L \times \sin \alpha$$

$$S = \frac{D-d}{2} \times \frac{L}{l}$$

#### 15.4. Procedure of processing threads.


15.4.1 Before the threads cutting, get the tools ready first.

The ordinary specifications of the threads are  $60^\circ$ ,  $55^\circ$ , and  $30^\circ$  trapezoid threads, etc.

15.4.2 Check the table plate on the change gear base, in the

lighte of the direction of 800 part to collocate change gears.

15.4.3 Get the needed size for the outer diameter of the threads cutting, check the right thread pitch to make sure its no error, then repeat the cutting till the nut can be screwed up.



## 16. TRANSPORTATION & INSTALLATION

### 16.1. Transportation

Avoid violent collision and fluctuation during loading, unloading and carrying, try to keep balance when hoisting, watch the cord or other things will not scrape the lead screw, spindle, hand wheels and other machine parts, the painted surfaces can't be scaped, for it will effect the outlook of the lathes.


### 16.2 Installation

The lathes can be fixed on the wooden or iron worktable


for operation, but the four braces for the worktable must be stable without inclination, in order that you can get the stable cutting without vibration and satisfy the processing accuracy durably.

## 17. ELECTRICAL PART

### 17.1 To open without cutting power device




220V—440v/50-60Hz 3PH




110V—240v/50-60Hz 1PH

17.2 To open with cutting power device




220V—440v/50-60Hz 3PH



110V—240v/50-60Hz 1PH


## 18. APPENDIX

### 18.1 HD250,HD210 Spindle Speeds Table











○ / min			
	A	B	C
II - I	620	1000	2000
III - I	125	210	420

### 18.2 Cq6125 Spindle Speeds Table










○ / min			
	D	E	F
II - I	620	1000	2000
III - I	125	210	420

# 18.3 HD250,HD210 Threading Table For Lnh Leads

$1/n$ 	8	9	10	11	12	14
B	80	90	70	70	70	70
D E	75 40	60 40	72 40	72 40	72	60 40
F $\rightleftarrows$	50	45	60	66	40	70
$1/n$ 	16	18	20	24	32	40
B	70	70	70	70	70	70
D E	60 40	60 80	60 80	50 40	45 80	30 40
F 	80	45	50	100	60	100
mm 	0.4	0.5	0.6	0.7	0.8	1
C B	68 80	68 80	68 80	68 40	68 80	68 80
D E	72 30	72 35	72 45	72 35	72 48	60
$\rightleftarrows$ F	75	70	75	100	60	72
mm 	1.25	1.5	1.75	2	2.5	3
C B	68 72	75 72	68 72	68 72	68 60	90 80
D E	80 60	80 68	80 70	80 70	72 75	72 68
F	48	50	40	35	40	30
		$1/n$ 		 0.005" 0.010"		
		C B		35 80 50 80		
		D E		90 30 66 30		
		F		100 100		

# 18.4 HD250,HD210 Threading Table For Metric Leadscrew

	0.4	0.5	0.6	0.7	0.8	1
G D	G 80	G 80	G 80	G 80	G 52	G 66
F E	30 80	30 60	30 50	42 60	60 80	60
L↔G	75 G	80 G	80 G	80 G	75 G	G 80
	1.25	1.5	1.72	2	2.5	3
G D	G 52	G 66	G 80	G 70	G 80	G 80
F E	75 80	75 80	70 80	80	75 80	75 25
L↔G	60 G	50 G	40 G	G 40	30 G	80 G
	10	11	14	19		
G D	G 80	G 80	G 80	G 80		
F E	66 40	60 40	75 50	50 40		
L G	52 G	52 G	66 G	75 G		
	20	22	40	44		
G D	G 60	G 80	G 80	G 80		
F E	66 80	60 80	33 52	30 52		
L G	52 G	52 G	80 G	80 G		
		mm				
			0.1	0.2		
		V D	33 80	50 80		
		F E	90 36	90 33		
		G L	G 90	G 90		





18.5 CQ6125 Threading Table for Inch Leadscrew

Threading Table for Inch Leadscrew

D	40	40	48	40	40	40	40
F Z	90 75	80 70	80 70	80 70	80 70	80 70	80 68
G E	45 40	45 40	40 57	50 40	55 40	60 40	70 40
BII	8	9	9 1/2	10	11	12	14
CII	16	18	19	20	22	24	28
AII				25		30	35

D	40	48	40	40	40	40	48
F Z	75 70	60 70	60 70	60 70	48 80	50 72	60 50
G E	50 60	45 72	50 57	75 40	66 40	75 40	72 70
CII	32	36	38	40	44	48	56

D	E	F	G	H	L	AI	AII	AIII	BI	BIII	CII	CIII
35	70	68	72	30	90	0.175	0.1	0.25			0.125	
40	60	68	72	45	75			0.6		1.5	0.3	0.75
40	60	68	72	48	60			0.8		2	0.4	1
50	60	68	72	48	60	0.7	0.4	1	1.75	2.5	0.5	1.25



# 18.6 CQ6125 Threading Table for Metric Leadscrew

Threading Table for METRIC Leadscrew										
mm										
D	E	F	G	A I	A II	A III	B I	B III	C II	C III
40	80	30	90	0.175	0.1	0.25			0.125	
40	60	48	80			0.6		1.5	0.3	0.75
30	75	60	45			0.8		2	0.4	1
40	48	60	75	0.7	0.4	1	1.75	2.5	0.5	1.25

1" / n						
Z	75		70		55	50
E	40	45	50	55	60	70
B II	8	9	10	11	12	14
C II	16	18	20	22	24	28
A II			25		30	35

--	--

# 18.7 CQ6125 Threading Table for Metric Leadscrew

	A	B	C		A	B	C
I	0.175		0.219	I			
II	0.1	0.25	0.125	II		0.6	0.3
III				III		1.5	0.75
	A	B	C		A	B	C
I	0.7	1.75		I			
II	0.4	1	0.5	II		0.8	0.4
III	1	2.5	1.25	III	0.8	2	1