

ENGINE & PROP:

Lycoming O-320-E2A, 150-HP, S/N L-19600-27A (Original Motor) 1071-SMOH (1996), 2000-TBO, 2017 Compressions: 79, 76, 78, 79 Sensenich 74DM6-0-62 2-Blade Prop, Hub S/N K26945 TTP Unknown, 831-SPOH, Installed in 1991

AVIONICS (IFR EQUIPPED):

Bendix/King KX-155 Digital Nav/Com VHF Transceiver #1 Bendix/King KX-155 Digital Nav/Com VHF Transceiver #2 Bendix/King KI-209 Nav Indicator (VOR/LOC/GS)

Bendix/King KI-208 Nav Indicator (VOR/LOC)

Bendix/King KLN-94 GPS

Bendix/King KMA-24 Audio Panel with 3 LMB Bendix/King KR-87 ADF with KI-227 Indicator

Bendix/King KN-64 DME

Precision Aviation PAI-700 Vertical Card Compass

Avionics Master Switch EI SR-8A Smart Analyzer

Narco AT-150 Transponder ACK E-01 ELT
Narco AR-850 Encoder TELEX TC-200 Intercom
Push-to-Talk Switches (Yokes) DATCON Hour Meter

EQUIPMENT:

Brackett Air Filter Post (Instrument) Lights

Rudder Trim Slick Mags
LED Landing Light Wingtip Strobes
Clock Beacon Light
Overhead Courtesy Light Sun Visors

Cabin Speaker Courtesy Step & Handle

Wind Scoop (Pilot Window)

Skytec Starter

Cabin Heat

Unleaded MOGAS STC

Stainless Steel Screws METCO AIRE Fiberglass Wingtips
Horton Flap & Gap Seals Laminar Flow Landing Gear Fairings

Wing Root Seals Polished Spinner

EXTERIOR:

Maroon with Silver Stripes on Matterhorn White Base, Rated 6/10

INTERIOR:

Maroon Vinyl Interior, Rated 6/10

LOGBOOK NOTATIONS:

2017: ACF-50 Corrosion X Treatment

1990: Repairs to Rudder Documented on Form 337







Great Scots Aircraft

Air Transportation for the Discriminating Flyer

Kevin McCray: (321) 210-0456 www.Greatscotsaircraft.com sales@greatscotsaircraft.com Asking Price: \$25,000 USD

Specifications subject to verification upon inspection Aircraft is subject to prior sale

Additional Information for N3578K:

Aircraft Based in FL, VA, NC According to Logbooks.

1990: TOP OVERHAUL. SUPERIOR ECI CYLINDERS Installed. Exterior was Stripped and Repainted Using Sikken Products. Collision Repairs – Rudder Skin Replaced, New Fin Installed, Aft Fuselage Assembly (Aft Section) Upper Skin Replaced.

2015: New Brakes Installed.

2016: Overhauled Vacuum Pump Installed.

2017: 3 New Tires, New Wire Harness Installed, Overhauled Carburetor Installed, L Mag Replaced.

AD 2013-02-13 C/W: Turnbuckle Inspection; Next Due March 2020 or 6250-TT.

Aircraft Idle from May 1996-February 1999.

Hours Flown Between Annuals:

2015 -2016: 75 2016-2017: 83 2017- Now: 41