

FermZilla Leaking lid



The problem seems to be on the tooling line, there is a small ridge

Inside the o-ring seat, where the injection moulding tool is not quite aligned and leaves a small step. I think that could be the problem.

This is happening on both sides of the lid.



Fortunately, this can be quite easily fixed.

Just use a small key file to smooth out the step, then use some 400 followed by 1000 grid sand paper to polish it out.

Do this gently and it is like the step never existed.

After sanding and polishing.



I believe this will fix the leak.

However, if this is still not working. You can place a second o-ring under the lid like this (spare o-ring comes with the kit).

But I think this is a over kill and I would only use it if the above does not work.

