


The remainder of the lever action will depend on the location of pipes and valves


| Par | t:   | Governor Assembly |   |     | Material |              | 9 |
|-----|------|-------------------|---|-----|----------|--------------|---|
|     |      |                   | Title William Fairbairn 10hp Steam Engine |     |          |              |   |
| REV | DATE | DESCRIPTION       | Scale                                     | NTS | Date:    | 26 July 2011 | 4 |




## © BOB HOLME


Engineering Service and Repair
Mobile: AU 0466 979 291
Int 61+466 979 291
Email: Maryak@homemodelenginemachinist.com







**Pivot Support Bracket** 



| D = =1 |      |                     |       |                            |          |             |              |  |
|--------|------|---------------------|-------|----------------------------|----------|-------------|--------------|--|
| Part:  |      | Brackets and Bushes |       |                            | Material | Brackets    | Mild Steel   |  |
|        |      |                     |       |                            |          | Bushes      | Bronze.      |  |
|        |      |                     | Title | William Fairbairn 10hp Ste |          | np Steam Er | am Engine    |  |
| REV    | DATE | DESCRIPTION         | Scale | 1:1                        |          | Date:       | 26 July 2011 |  |



## **BOB HOLME**

Engineering Service and Repair Mobile: AU 0466 979 291 Int 61+466 979 291 Email: Maryak@homemodelenginemachinist.com

