THREADS PER INCH	WHEN TO ENGAGE
TO BE CUT	SPLIT NUT
Even Number	Engage At Any
Of	Graduation On
Threads	The Dial
Odd Number Of	Engage At Any
Threads	Main Division
Fractional Number	1/2 Threads, E.G. 11 1/2
Of	Engage At Any Other
Threads	Main Division 1&3, Or 2& 4
	Other Fractional Threads
	<b>Engage At Same Division</b>
	Every Time
Threads That Are A	
Multiple of The	Engage At Any Time That
Number of The	Split Nut Meshes
Threads per Inch	-
In The Lead Screw	i

Diagon 7 00 minus 1 de circo distribuido de care