

\$155,000.00
1978 Piper Lance N432DP
PA-32RT-300T
S/N 32R-7887092
3210 hrs SNEW
1535 hrs SMOH
252 hrs STOP
367 hrs SPOH
Turbo Charged
Turbo Plus Intercooler
Paint 8
All new Leather Interior 10 installed, new 2014 and headliner
6 Place Club Seating
Piper Air Conditioning
3 position Strobe Lights
LED Landing light
SkyOx oxygen system (Aluminum bottle, needs to be recertified)
Annual due 12-31-2021
IFR cert due 3-31-2023
All logs since new
New 2 blade Prop and HUB installed 2003 eliminates reoccurring hub AD 2003,
No Damage History
Tanis engine Pre-Heat System (All cylinders, oil sump, and air manifold)
Electric trim
New Sky Tec Starter 08/2009
Auxiliary Power outlet
Jumper Cables
Precise Flight Standby Vacuum System
Hobbs Meter
Stratus USB Power Supply
406Mhz ELT
Jumper Cables with Piper plug

Avionics Panel
Avionics Master
GNS 530W
KXY155 w/GS
2 Garmin G5s with GPSS
GAD13 TAS and winds aloft
Century IIC Altimatic auto pilot with altitude hold
GTX-330 ES (ADS-B out certified, 2020 compliant)
KMA-24 Audio Panel
Precise 4 place Intercom
Strike Finder Lightning System
TIS traffic displayed on GNS-530

JPI 830 Engine Monitor with Fuel Flow wired to GNS530W

Pilot's Yoke-mounted 'Autopilot Interrupt' 'Electric Trim' & 'Push-to-Talk'
Switches

Co-Pilot's Push-to-Talk Switch